

**City of Upper Sandusky**

**CSO Four-Hour Public Notification Form**

Point of Contact: City of Upper Sandusky, Wastewater Treatment, Aaron Putnam, 419-209-0683

Date/Time of CSO Discovery: 4-26-19/7:30am

NPDES Permit Number: 2PD000390

CSO Discharge (Check All that Apply)	<b>X</b>	<b>X</b>		<b>X</b>				
<b>CSO Station Number</b>	<b>052</b>	<b>053</b>	<b>054</b>	<b>055</b>	<b>056</b>	<b>057</b>	<b>058</b>	<b>059</b>
CSO Location	W. Bank, Behind 777 N. Sandusky St.	E. Bank, SW Corner of 800 Mission Dr.	W. Bank, 633 N. 5th St.	W. Bank, East Edge of Golf Course	W. Bank, Rear of 333 S. 4th St.	W. Bank, South of 333 S. 4th St.	W. Bank, Rear of 513 S. Sandusky Ave.	W. Bank, North Side of High St.
Receiving Water Body	Unnamed Tributary of Sandusky River	Unnamed Tributary of Sandusky River	Unnamed Tributary of Sandusky River	Sandusky River	Sandusky River	Sandusky River	Sandusky River	Sandusky River
Date CSO Started	4-25-19	4-25-19		4-26-19				
Time CSO Started	5:45pm	5:50pm		4:55am				
Date CSO Ended*	CD	CD		4-26-19				
Time CSO Ended*	CD	CD		7:05am				

Notes:

\* - Enter "CD" if the CSO is still currently discharging at the time this notification is completed.

Comments: This event saw 0.8" of rain measured at the WRF at time of notification.